



HD-SDI Express PCIe Release Notes – 09/30/2013

- Changed firmware to version 0.4.0.1 (from 0.4.0.0).

Firmware – 0.4.0.1	Changes from version 0.4.0.0
1	Solved IRQ lock-up problem when there are lots of UART_Rx and DMA_DONE interrupts.
2	Changed UART RX_FIFO to use real FIFO instead of SRAM.
3	Made several performance improvements to UART receiver.